

SAFETY DATA SHEET

PC 41 VERT LUSTRE

1. Identification

Product identifier

Product name PC 41 VERT LUSTRE

Product number PC 41 VERT LUSTRE

Recommended use of the chemical and restrictions on use

Application ceramic glaze

Details of the supplier of the safety data sheet

Supplier American Art Clay Co Inc
6060 Guion Road
Indianapolis,
IN 46254-1222
USA
Toll Free: 1-800-925-5195 ext. 1303
Local: 1-317-243-0066 ext. 1303

Emergency telephone number

Emergency telephone 1 317 243 0066 ext. 1303 Mon-Fri, 0900-1700 EST

2. Hazard(s) identification

Classification of the substance or mixture

Physical hazards Not Classified

Health hazards Acute Tox. 4 - H302

Label elements

Pictogram



Signal word Warning

Hazard statements H302 Harmful if swallowed.

Precautionary statements P264 Wash contaminated skin thoroughly after handling.
P270 Do not eat, drink or smoke when using this product.
P301+P310 If swallowed: Immediately call a poison center/ doctor.
P330 Rinse mouth.
P501 Dispose of contents/ container in accordance with national regulations.

Supplemental label information WARNING: MAY BE HARMFUL IF SWALLOWED. Contains: COPPER. PRECAUTIONS: Keep in original container. Wash hands immediately after use. When using do not eat, drink or smoke. NOT FOR SPRAY APPLICATION. NOT FOR USE IN HEALTH CARE FACILITIES. KEEP OUT OF REACH OF CHILDREN. FIRST AID TREATMENT: If swallowed get prompt medical attention. For further information, contact a national poison control number; 800-222-1222.

Other hazards

none present

3. Composition/information on ingredients

PC 41 VERT LUSTRE

Mixtures

Copper Oxide	1-5%
CAS number: 1317-38-0	
Classification	
Unknown Classification	

The full text for all hazard statements is displayed in Section 16.

Composition comments Only ingredients listed above are notifiable for this product. If none are shown then all ingredients are exempt.

4. First-aid measures

Description of first aid measures

General information

--

Ingestion

Do not induce vomiting. Rinse mouth thoroughly with water. Give a few small glasses of water or milk to drink. Get medical attention if any discomfort continues.

Skin Contact

Wash skin thoroughly with soap and water.

Eye contact

Rinse with water.

Most important symptoms and effects, both acute and delayed

Inhalation

Read Section 2 for any specific precautions associated with this product. In general, breathing any type of dust / mist can and may aggravate irritation of the throat and lungs.

Ingestion

Read Section 2 for any specific precautions associated with the use of this product. Products with specific warnings about ingestion will give guidance there.

Skin contact

Read Section 2 for any specific precautions associated with the use of this product. In general most ceramic glazes, clays and special products will tend to have a drying effect on the skin and may cause some sensitivity to users with sensitive skin.

Eye contact

Read Section 2 for any specific precautions associated with the use of this product. In general most ceramic and special products contain materials that maybe abrasive to eyes. Keeping materials from contacting the eyes is prudent. If contact does occur, flush with clean water, do not rub.

Indication of immediate medical attention and special treatment needed

Notes for the doctor

Treat symptomatically.

5. Fire-fighting measures

Extinguishing media

Suitable extinguishing media

Use fire-extinguishing media suitable for the surrounding fire.

Special hazards arising from the substance or mixture

Specific hazards

The product is not believed to present a hazard due to its physical nature.

Advice for firefighters

Special protective equipment for firefighters

Use protective equipment appropriate for surrounding materials.

6. Accidental release measures

Personal precautions, protective equipment and emergency procedures

PC 41 VERT LUSTRE

Personal precautions For personal protection, see Section 8.

Environmental precautions

Environmental precautions Please read Section 2 completely. If any environmental warnings such as; H411 or H412 are listed in Section 2, please use appropriate procedures when disposing of product and container. Do not put materials into waterways or sewers.

Methods and material for containment and cleaning up

Methods for cleaning up Collect spillage for reclamation or absorb in vermiculite, dry sand or similar material

Reference to other sections For waste disposal, see Section 13. For personal protection, see Section 8.

7. Handling and storage

Precautions for safe handling

Usage precautions Read label before use. Do not eat, drink or smoke when using this product. Good personal hygiene procedures should be implemented. Wash hands and any other contaminated areas of the body with soap and water before leaving the work site.

Conditions for safe storage, including any incompatibilities

Storage precautions Store in tightly-closed, original container in a dry and cool place.

Specific end uses(s)

Specific end use(s) The identified uses for this product are detailed in Section 1.2.

8. Exposure Controls/personal protection

Control parameters

Ingredient comments Only ingredients listed in Section 3 are notifiable for this product. If none are shown then all ingredients are exempt.

Copper Oxide (CAS: 1317-38-0)

Immediate danger to life and health 100 mg/m³

Exposure controls

Appropriate engineering controls No specific ventilations requirements unless the "FAN" pictogram is shown above or specified in Section 2.

Eye/face protection No specific eye protection required unless the "EYE PROTECTION" pictogram is shown above or specified in Section 2.

Hand protection No specific hand protection required unless the "HAND PROTECTION" pictogram is shown above or specified in Section 2.

Hygiene measures Using good personal hygiene practices is always appropriate. Keeping a clean work space, cleaning up properly when done, and not eating, drinking or smoking when using this product.

Respiratory protection No specific respiratory protection required unless the "RESPIRATOR" pictogram is shown above or specified in Section 2. Using the appropriate certified protection for the operation is important if required.

9. Physical and Chemical Properties

Information on basic physical and chemical properties

Appearance Colored liquid.

PC 41 VERT LUSTRE

Color	Various colors.
Odor	Almost odorless.
Odor threshold	No information available.
pH	6-8
Melting point	No information available.
Initial boiling point and range	No information available.
Flash point	No information available.
Evaporation rate	No information available.
Flammability (solid, gas)	No information available.
Upper/lower flammability or explosive limits	No information available.
Vapor pressure	No information available.
Relative density	Greater than 1.0
Solubility(ies)	Not applicable.
Partition coefficient	No information available.
Auto-ignition temperature	Not applicable.
Decomposition Temperature	No information available.
Viscosity	No information available.
Explosive properties	none
Oxidizing properties	none
Other information	Not applicable.

10. Stability and reactivity

Reactivity	There are no known reactivity hazards associated with this product.
Stability	No particular stability concerns.
Possibility of hazardous reactions	None known.
Conditions to avoid	None known.
Materials to avoid	None known.
Hazardous decomposition products	None known.

11. Toxicological information

Information on toxicological effects

Toxicological effects Please read Section 2 thoroughly to understand the toxicological risks, (if any) and precautions for safe use (if any).

Acute toxicity - oral

PC 41 VERT LUSTRE

ATE oral (mg/kg) 500.0

Acute toxicity - inhalation

ATE inhalation (dusts/mists mg/l) 71.43

Skin corrosion/irritation

Skin sensitization

Skin sensitization Please read Section 2 thoroughly to understand the toxicological risks (if any) and precautions for safe use (if any).

Eye contact May cause temporary eye irritation.

12. Ecological Information

Ecotoxicity Please read Section 2 completely. If any environmental warnings such as; H411 or H412 are listed in Section 2, please use appropriate procedures when disposing of product and container. Do not put materials into waterways or sewers.

Toxicity

Persistence and degradability

Persistence and degradability No data available.

Biodegradation Not inherently biodegradable.

Bioaccumulative potential

Partition coefficient No information available.

Mobility in soil

Mobility Semi-mobile.

Results of PBT and vPvB assessment

Results of PBT and vPvB assessment This product does not contain any substances classified as PBT or vPvB.

Other adverse effects

Other adverse effects None known.

13. Disposal considerations

Waste treatment methods

General information Dispose of waste product or used containers in accordance with local regulations. When handling waste, the safety precautions applying to handling of the product should be considered.

14. Transport information

General The product is not covered by international regulations on the transport of dangerous goods (IMDG, IATA, DoT).

UN Number

Not applicable.

UN proper shipping name

Not applicable.

PC 41 VERT LUSTRE

Transport hazard class(es)

No transport warning sign required.

Packing group

Not applicable.

Environmental hazards

Environmentally Hazardous Substance

Please refer to Section 2 for any environmental hazards associated with this product. If H411/H412 warnings are shown then please verify packaging and labeling requirements for larger volumes.

Special precautions for user

Not applicable.

Transport in bulk according to Not applicable.

Annex II of MARPOL 73/78

and the IBC Code

15. Regulatory information

International Regulations

US State Regulations

California Proposition 65 Carcinogens and Reproductive Toxins

None of the ingredients are listed or exempt.

Massachusetts "Right To Know" List

calcium carbonate and dolomite

1-5%

Hydrated Aluminium Silicate

1-5%

silica

10-30%

2-aminoethanol

<1%

Rhode Island "Right To Know" List

calcium carbonate and dolomite

1-5%

Hydrated Aluminium Silicate

1-5%

silica

10-30%

2-aminoethanol

<1%

Minnesota "Right To Know" List

calcium carbonate and dolomite

1-5%

Hydrated Aluminium Silicate

1-5%

PC 41 VERT LUSTRE

silica
10-30%

2-aminoethanol
<1%

New Jersey "Right To Know" List

calcium carbonate and dolomite
1-5%

Hydrated Aluminium Silicate
1-5%

manganese dioxide
1-5%

silica
10-30%

2-aminoethanol
<1%

Pennsylvania "Right To Know" List

calcium carbonate and dolomite
1-5%

Hydrated Aluminium Silicate
1-5%

silica
10-30%

2-aminoethanol
<1%

Inventories

Canada - DSL/NDSL

All the ingredients are listed or exempt.

US - TSCA

All the ingredients are listed or exempt.

US - TSCA 12(b) Export Notification

All the ingredients are listed or exempt.

16. Other information

General information	The following are the top 5 materials by weight listed for New Jersey (if applicable):- Water 7732-18-5, Feldspar68476-25-5, Non Lead Frit65997-18-4, Nepheline Syenite37244-96-5 Gillespie Borate
Revision date	7/25/2016
Revision	37
Supersedes date	7/20/2016
SDS No.	5446
Hazard statements in full	H302 Harmful if swallowed.

PC 41 VERT LUSTRE

This information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process. Such information is, to the best of the company's knowledge and belief, accurate and reliable as of the date indicated. However, no warranty, guarantee or representation is made to its accuracy, reliability or completeness. It is the user's responsibility to satisfy himself as to the suitability of such information for his own particular use.